

Care Instructions for Clear PVC

Flexible Clear PVC

Stock Code PVK and PVNYC

These instructions will maintain the appearance and extend the functional life of the fabric.

Do not

- Dryclean
- Iron
- Use a stiff brush, vigorous rubbing or tumble drying
- Use abrasive cleaners
- Allow contact with petrol, acetone or other similar products which may attack the PVC

General Care

Vacuum regularly using low suction to remove loose dirt.

Clean regularly with hot or warm soapy water and a soft brush, or lightly sponge down with warm water. Allow to dry thoroughly before storage or re-use.

Spot Cleaning/Special Treatments

Treat stains as soon as possible. Test on an inconspicuous area first before proceeding.

Mildew may be removed by wiping with a cold solution of sodium hypochlorite having 4% chlorine, in the proportion of 1 part to 4 of water. Rinse thoroughly with cold water.

Grease spots may be removed carefully by rubbing lightly with a soft cloth and some ethanol (ethyl alcohol).