



Care Instructions for Toptarp®

Reinforced PVC

Stock Code PVTT and PVTS

These instructions will maintain the appearance and extend the functional life of the fabric.

Do not

- Use solvents, abrasives or harsh detergents to clean
- Dryclean
- Iron

General Care

A regular wipe over with warm soapy water followed by rinsing with cold water will remove normal soiling. Where a buildup has occurred, the surface should be cleaned with a soft brush and mild, non abrasive detergent, then rinsed thoroughly.

Spot Cleaning/Special Treatments

Mildew may be removed by wiping with a cold solution of household chlorine bleach having 4% chlorine, in the proportion of one part in four to water. Rinse thoroughly with cold water.

